#### **DEPARTMENT OF TRANSPORTATION**

DIVISION OF ENGINEERING SERVICES Office of Structural Materials Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

69.28 File #:

## WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-002365 Address: 333 Burma Road **Date Inspected:** 15-May-2008

City: Oakland, CA 94607

OSM Arrival Time: 2000 **Project Name:** SAS Superstructure **OSM Departure Time:** 700 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai China

**CWI Name:** N/A **CWI Present:** Yes No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No N/A No Yes N/A **Weld Procedures Followed:** N/A **Electrode to specification:** No Yes No Yes N/A N/A **Qualified Welders:** No **Verified Joint Fit-up:** Yes No N/A Yes No N/A **Approved Drawings:** Yes No **Approved WPS: Delayed / Cancelled:** Yes No N/A

34-0006 **Bridge No: Component:** Deck Panel

### **Summary of Items Observed:**

The Caltrans QA Inspector Mr. David Kelsey performed Visual Testing (VT) on DP165-001 partial penetration welds 001 thru 010. This inspector marked and measured visual indication such as under-fill, overlap, oversized, undersized and incomplete fusion. Results were recorded on the deck panel inspection form and copies turned into the appropriate personnel and deck panel log book. No other observation took place during the shift by this inspector.



**Description WBS** Dwg No. Status Item

Above picture

# WELDING INSPECTION REPORT

(Continued Page 2 of 2)

Visual Inspection of the partial penetration welds for DP165-001 welds 001 thru 010.

## **Summary of Conversations:**

None noted.

### **Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Mazen Wahbeh, (818) 292-0659, who represents the Office of Structural Materials for your project.

Inspected By:	Kelsey,David	Quality Assurance Inspector
Reviewed By:	Cochran,Jim	QA Reviewer